




Plan View



Locked Position



Elevation View



Unlocked Position

Drawing is not a template, use as reference.

Installation Instructions:

1. Screw backplate to face of door by swinging latch to unlocked position. When latch is in the locked position all screws on the backplate should be concealed.
2. With latch in locked position, align holes for padlock on swivel plate and eye. Fasten eye and ensure all screws will be covered when latch is in locked position.
3. To prolong life of product, painting the product and oiling on a regular basis is recommended.



DWG #: 0002479
 DRAWN:BCM 5/10/2017
 SHEET #2
 File: 0002479.idw

ALL DIMENSIONS IN INCHES

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF CROWN INDUSTRIAL. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF CROWN INDUSTRIAL IS PROHIBITED.	ID #:	STOCK PART #:
	0002473	431
DESCRIPTION:		
Swivel Locking Bar Latch: Parrellel Mount Option		
FINISH:	# PCS:	REV:
Clear Zinc	1	



CROWN INDUSTRIAL
 So. San Francisco, Ca
 (650) 952-5150
 www.crown-industrial.com



ALL DIMENSIONS IN INCHES

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF CROWN INDUSTRIAL. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF CROWN INDUSTRIAL IS PROHIBITED.	ID #:	0002478	STOCK PART #:	431
	MATERIAL:			
DESCRIPTION: Latch: Perpendicular Mount Option				
FINISH:			# PCS:	1
			REV:	



CROWN INDUSTRIAL
 So. San Francisco, Ca
 (650) 952-5150
www.crown-industrial.com

DWG #: 0002479
 DRAWN: BCM 5/10/2017
 SHEET #3
 File: 0002479.idw